



Main Blower Motor Replacement – Part Number 57288

Affected Models

- PS638E
- PS638G
- PS640E
- PS640G

Subject

Main Blower Motor – Part Number 57288

Overview

Two different styles of main blower motors are currently approved for use on the affected oven models listed above. Both motors are factory approved and fully interchangeable.

The two approved motor styles are:

- Lincoln motor (Grey)
 - Nidec FIR motor (Silver)
-

Important Installation Information

If the oven is currently equipped with the Lincoln (grey) motor and is being replaced with the Nidec FIR (silver) motor, the included mounting bracket must be installed during replacement.

Failure to install the mounting bracket may result in improper motor fitment or alignment.

Service Notes

- Both motor styles are approved for use by the factory.
- Technicians may receive either motor style depending on availability.
- The Nidec FIR (silver) motor includes the required mounting bracket in the box.

Action Required

When replacing main blower motor part number 57288:

1. Verify the existing motor style installed in the oven.
2. If replacing a Lincoln (grey) motor with a Nidec FIR (silver) motor:
 - o Install the included mounting bracket.
3. Confirm all mounting hardware is properly secured before returning the oven to service.

For additional technical support, please contact the Technical Support Department.

847-429-7852

service@middleby.com