

RTS

Einbauanleitung NR.:
Installation Instruction No.:

03_05

Thema / Subject: **Software XS5_06S**

Datum / date: **28.08.2003**

Zusatzinfo zur Software Version XS5_06S

Wird diese Software Version in Geräten eingesetzt in denen die Software Version XS5_03 oder älter installiert war, bitte darauf achten, dass bei CleanJet Nutzung veränderte Anzeigen erscheinen. (Alte Software: **Abbruch**; neue Software: **Spülen Start, Service5** und **Service6**).

Bitte informieren Sie den Kunden über die Veränderung und händigen Sie ihm beigefügtes Blatt aus.

Additional information Software Version XS5_06S

When you install this Software Version to a unit where Software Version XS5_03 or older was installed, please bear in mind that in CleanJet mode different indications are shown. (old Software: **Abort**; new Software: **Rinse Start, Service5** and **Service6**).

Please inform your customer and hand over attached sheet.

Technische Dokumentation

Important User Information!

The following error messages may appear on the display:

Message:	What can you do?
ABORT	Make sure CleanJet arm is correctly inserted. Close cabinet door. Make sure enough chemical is present in both Detergent <u>and</u> Rinse container. Press START key and allow unit to rinse for 4 minutes. If ABORT does not disappear, call your local Rational Service Partner.
Rinse Start	Make sure CleanJet arm is correctly inserted. Close cabinet door. Make sure enough chemical is present in both Detergent <u>and</u> Rinse container. Press START key and allow unit to rinse for 4 minutes. Should "Service 5" appear after several attempts: see below.
Service 1	After 2 minutes of waiting time all operations including IQT and Program Start are fully functional. Call your local Rational Service Partner for urgent Steam generator maintenance
Service 3	After 2 minutes of waiting time all operations including IQT and Program Start are fully functional. Call your local Rational Service Partner for IQT Sensor maintenance NOTE: IQT programs are not running with full performance.
Service 4	After 2 minutes of waiting time all operations including IQT and Program Start are fully functional. Call your local Rational Service Partner for IQT Sensor maintenance NOTE: IQT programs as well as manual programs with core probe are not running anymore.
Service 5	Function is disabled until "Service 5" is deleted. CleanJet Rinse program did not complete full cycle. Make sure there is enough Rinse liquid in the Cleanjet Container! To delete "Service 5" indication: Rinse cabinet thoroughly with hand shower! Close the cabinet door. Press simultaneously Cabinet temperature key, Timer and IQT key to delete "Service 5" indication. If "Service 5" appears again call your local Rational Service Partner for Cleanjet maintenance
Service 6	Function is disabled until "Service 6" is deleted. Call your local Rational Service Partner for Cleanjet maintenance To delete "Service 6": Rinse cabinet thoroughly with hand shower! Close the cabinet door. Press simultaneously Cabinet temperature key, Timer and IQT key to delete "Service 6" indication.
Buzzer sounds intermittent	Call your local Rational Service Partner for urgent general maintenance. Unit out of function.
Gas Units: RESET (CM – rES)	Make sure the gas shut-off valve is open! Make sure venting hood is switched on and operational! Reverse Power plug polarity (if applicable!) Switch off unused gas equipment in the kitchen (as gas pressure might be too low) If "RESET" does not disappear, call your local Rational Service Partner.

Was tun wenn.....?

Eine der folgenden Fehlermeldungen angezeigt werden:

Fehlermeldung:	Was tun??
Abbruch	CleanJet Arm ordnungsgemäß einhängen. Garraumtür schliessen. Sicherstellen dass genügend Reiniger und Klarspüler im CleanJet tank vorhanden ist.. Start Taste drücken.. Der CPC startet ein 4 min. Ausspülprogramm. Sollte die „Abbruch“- Meldung bestehen bleiben rufen Sie ihren zuständigen Rational Service Partner
Spülen Start	CleanJet Arm ordnungsgemäß einhängen. Garraumtür schliessen. Sicherstellen dass genügend Reiniger und Klarspüler im CleanJet tank vorhanden ist.. Start Taste drücken.. Der CPC startet ein 4 min. Ausspülprogramm. Sollte die Meldung „Service 5“ erscheinen: siehe unten.
Service 1	Nach 2 Minuten Wartezeit sind die Funktionen IQT und Programm Start nutzbar. Beauftragen Sie Ihren Rational Service Partner mit einer dringenden Wartung des Dampferzeugers.
Service 3	Nach 2 Minuten Wartezeit sind die Funktionen IQT und Programm Start nutzbar. Beauftragen Sie Ihren Rational Service Partner mit einer dringenden Reparatur des IQT Sensors. ACHTUNG. Die IQT Programme sind nicht voll einsatzfähig.
Service 4	Nach 2 Minuten Wartezeit sind die Funktionen IQT und Programm Start nutzbar. Beauftragen Sie Ihren Rational Service Partner mit einer dringenden Reparatur des IQT Sensors. ACHTUNG. Die IQT Programme sowie manuelle Programme mit Kerntemperatur sind nicht nutzbar!
Service 5	Die Funktion des Gerätes ist solange gesperrt, bis „Service 5“ quittiert ist. Das CleanJet Ausspülprogramm wurde nicht ordnungsgemäß beendet. Stellen Sie sicher dass genügend Klarspüler im Gerät vorhanden ist! So quittieren Sie die "Service 5" Anzeige: Garraum gründlich mit der Handbrause ausspülen! Garraumtür schließen. Drücken Sie gleichzeitig die Tasten: Garraumtemperatur, Uhr und IQT. Sollte die „Service 5“-Meldung bestehen bleiben rufen Sie ihren zuständigen Rational Service Partner
Service 6	Die Funktion des Gerätes ist solange gesperrt, bis „Service 6“ quittiert ist. Beauftragen Sie Ihren Rational Service Partner mit einer dringenden Wartung des CleanJet systems. So quittieren Sie die "Service 6" Anzeige: Garraum gründlich mit der Handbrause ausspülen! Garraumtür schließen. Drücken Sie gleichzeitig die Tasten: Garraumtemperatur, Uhr und IQT.
Summer hupt	Beauftragen Sie Ihren Rational Service Partner mit einer dringenden Wartung ihres Rational Combi's. Gerät ist ohne Funktion
Gasgeräte: RESET (CM – rES)	Gasabsperrhahn öffnen! Abzugshaube einschalten und Funktion prüfen! Netzstecker drehen (falls vorhanden). Nicht genutzte Gasverbraucher in der Küche abstellen (evtl. Gasdruck zu gering) Sollte die „RESET“-Meldung bestehen bleiben, rufen Sie ihren zuständigen Rational Service Partner