


# REPLACEMENT RELAY




It has been necessary to change our relay design and the following should be noted when fitting a replacement. Wire numbers may vary, however these should be connected as follows

IMO Relay	Terminal	Schrack Relay	Terminal	Finder Relay	Terminal
Wire to	4	Wire To	4	Wire to	8
Wire to	5	Wire to	6	Wire to	2
Wire to	7	Wire to	7	Wire to	6
Wire to	8	Wire to	9	Wire to	4
Wire to	A	Wire to	A	Wire to	A2
Wire to	B	Wire to	B	Wire to	A1


**IMO Relay**



**Schrack Relay**



**Finder Relay**



## Falcon Foodservice Equipment

HEAD OFFICE AND WORKS

Wallace View, Hillfoots Road, Stirling. FK9 5PY. Scotland.

SERVICELINE CONTACT

t: 01438 363 000 f: 01438 369 900

T100782 Ref.3